4 5 6	7
-------	---

Flag Country IMO ID Number Date of ECA First Notice Location of ECA First Notice

SNG 9626120 27-Aug-14 Pyeong Taek

8 9 10

Name of Ports after First Notice Name of Last Port before ECA Entry Name of Port with Fuel Oil Supply Disruption

Pyeong Taek - Stewart Pyeong Taek -

Name of Original Fuel Supplier with Disruption Number of Fuel Suppliers Contacted

1 - LSF was supplied, but initial testing indicated off spec bunkers.

15	14	13
Sulfur Content of Non-Compliant Fuel Oil	Time of Entry in the ECA	Date of Entry in the ECA
3.14%	11:45 UTC	20-Sep-14

16 17 18

Projected Hours on Main Propulsion Name of First POC Compliance Fuel Oil Available at First POC?

108 hrs Stewart, BC no

19	20
Plan to Bunker Compliant Fuel Oil at First POC?	Number of fuel suppliers contacted at First POC
no	0

Name of Second POC Compliant Fuel Oil at Second POC? Plan to Bunker Compliance Fuel Oil at Second POC?

Hawk Inlet, Alaska no no

23

24 25 26

Number of Fuel Suppliers Contacted at the Second POC? Date of Exit from ECA? Time of Exit from ECA?

0 12-Sep-14 12:00 UTC

27			28

Has this vessel operated in the ECA in previous 12 months?	Number of Separate Visits to the ECA	
yes	1	

29	30	31
Number of Ports visited in the ECA	Previously submitted ECA0100 forms?	Number of Submitted Reports
1	no	0

Designated Corporate Official Name Designated Corporate Official E-mail

Frank Busacker@Oldendorff.com

Designated Corporate Official Phone Number

49 451 1500 112

Description of Actions to Achieve Compliance

LSF was supplied in Pyeong Taek, but after testing the bunker, initial results indicate off spec bunkers (Aluminum and Sili